

# MONUMENT RECORD


Corner I.D. #

W-17

STATE OF INDIANA - COUNTY OF MONROE

Section Twenty-four, 24, Township 8 North, Range 2 West

**Monument Description & Remarks:** Found 1" crimped iron pipe, loose & leaning at South 1/4 corner. Pipe was firmed & straightened. Survey marker sign nailed in fence post; 1/2" rebar found S 58° W, 0.25' from pipe (corner).



State of Indiana  
County of Monroe

I, Michael W. Friley, County Surveyor Monroe, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 10th day of March, 1995 A.D.

Space  
Reserved For  
Recording  
Officer

Indiana Registered Land Surveyor No. \_\_\_\_\_ or

Office of Monroe County Surveyor  
United States Government Agency

Monroe County Surveyor  
Title

Field Book:

95-01

Page:

14